#### standard welding tools

#### standard welding tools



#### M50 welding iron

Thermostated, for round, V and flat belts up to 50 mm wide. 200 W.



## M 51 welding iron with teflon-covered blade

Thermostated, for round and V belts up to 22 x 14 mm. 200 W.



### standard weld ing tool case



# For round

and V belts



#### J50 welding clamp

For round and flat belts up to 50 mm wide.




#### J25 welding clamp

For V belts up to 25 x 16 mm.



#### J15 welding clamp

Small clamp for round belts up to diam. 10 mm.



## P10 cutting clamp

To clean weldings.



#### **Tensioning tools**

For round and V belts. Includes 2 clamping dies and 1 winch with lever.

#### Includes:

- 1 M51 welding iron
- 1 J50, J60 or J15 welding clamp
- 1 \$135 cutter
- 1 P10 cutting clamp



#### S135 cutter

For 90° and 45° cuttings.



36